



Figure D-15. Transport vehicles on the road.



Figure D-16. Loading contaminated soil.





Figure D-17. Aerial view of ARA-12 in Spring 2004.



Figure D-18. Aerial view of ARA-23 in Spring 2004 with ARA-01 in the distance.





Figure D-19. Soil scraper.



Figure D-20. Laying haul road at ARA-23.





Figure D-21. Laying haul road at ARA-12.



Figure D-22. Dust suppression of new haul road at ARA-23.





Figure D-23. Removing fence at ARA-II.



Figure D-24. ARA-II following fence removal.





Figure D-25. Windrowing soil at ARA-23 with excavated concrete rubble pile in background.



Figure D-26. Windrowing soil at ARA.23.